

Stream Monitoring Report

STREAM MONITORING

The Pacific Lumber Company has an extensive three year old watershed monitoring program. We have installed 52 permanent stations. At each station we measure aquatic macroinvertebrates, fine sediments, substrate size and crown cover. At a subset of these stations we also measure continuous temperature and surveying the stream bed. We now have a better understanding of the condition of our streams. More importantly, these stations are a benchmark against which to measure change over time. We are developing relationships between the condition of the stream and the health of the entire watershed.

Aquatic macroinvertebrates have been widely used for decades in America and around the world as a cheap and effective way to assess water quality. We are using as a guide, the California Stream Bioassessment Procedures prepared by Jim Harrington of the Department of Fish and Game. The samples are being identified by Lauck, Lee and Lauck Inc.

Sediment samples are being used to assess the percent of fines (<0.85mm) as an indicator of suitability for Salmon spawning. We are using the shovel sample technique as described in "Field Comparison of Three Devices Used to Sample Substrate in Small Streams" by Grost and Hubert, 1991.

Pebble counts are being used to estimate whether the stream is sediment loaded. Sediment loading can effect spawning gravels and fill in pools. We are using the method described in "Stream Reference Sites" Harrelson, Rawlins and Potyondy, 1994, RM-245.

On a subset of the plots we have measured water temperature over the summer using continuous recording thermometers (Hobos or Stowaways).

Crown cover percent has been estimated using a spherical densiometer.

In 1996 we surveyed the stream bed of 12 of the stations using a method developed by Dr. Bill Trush in cooperation with Simpson Timber Company. We used an engineer's level and surveyed the bottom of the channel at the thalweg. We expect this to be a quantitative index of habitat quality. The more pools and structure (deep, dark and dense) a stream has, the greater the coefficient of variation around the mean should be. By setting a permanent benchmark, we can remeasure in the future for aggradation and degradation.

The Inland Fisheries Division of the Department of Fish and Game maintains 12 permanent monitoring stations on our property. Due to sample design problems in sediment collections, we have deleted state sediment collections from 1992 to 1995. They also provided some regional data that will allow us to better assess what is normal.

The following assessment is a compilation of existing data. It includes data from across PL's property and across the north coast region. This larger view helps us to put into perspective site specific information and help us better understand what the range of normal conditions are in our north coast streams.

This information is summarized by year, by stream, by planning watershed, by larger river system. An We are using planning watersheds that were mapped and provided by the Resources Department.. Planning watersheds are defined in the rules under 895.1. Their use is encouraged under 897(b)(1)(B), 916.8, 1091.3 and 1091.4.

AQUATIC MACROINVERTEBRATES

The use of macroinvertebrates as indicators of stream condition is a well accepted and long established method (Erman, N, 1991). An inventory of macroinvertebrate fauna in stream riffles can measure changes in chemical and physical stream properties. These changes ultimately determine the presence and distribution of resident biota (Usinger, 1956). Such an inventory is indicative of current as well as past environmental conditions. This method of sampling emphasizes the collection of bottom dwelling insects, which are relatively fixed in their habitat, unlike fish or plankton which can move to more favorable conditions (Usinger, 1965).

Richness

This is a measure of the total number of taxa or groups of taxa. Insects are grouped down to the Genus level. The **Richness** metric and the **EPT Index** are measures of richness. Taxa richness generally decreases with decreasing water quality (Weber, 1973; Resh and Grodhaus, 1983). The following table will help describe the quality of the stream when Genus Richness is used as a metric. (Personal Com. Jon Lee, 1994):

	Poor	Average	Good
Richness	<25	25 to 34	>35

Community Diversity Index

The most common measures of stream health are diversity indices. Diversity indices measure species richness rather than abundance. A healthy stream should exhibit high diversity evidenced by a large number of taxa without any one taxon dominating.

The **Simpson** diversity index is the most commonly used diversity index when addressing aquatic communities (Magurran, 1988, Rosenberg and Resh, 1992).

The **Simpson** index is based upon species dominance. The **Simpson** diversity index ranges from 0 - 1.0. As the index approaches 1.0, the more diverse the sample is thought to be. The following table will help describe the quality of the stream when the Simpson index is used (Personal Com. Jon Lee, 1994):

	Poor	Average	Good
Simpson Diversity Index	.7 to .79	.8 to .89	.9 to 1.0

.

Enumerations

This tries to measure balance between the groups of insects.

The **Ephemeroptera**, **Plecoptera**, **Trichoptera** (**EPT**) and **Chrionomidae** ratio uses relative abundance of these indicator groups as a measure of community balance. A good biotic condition is reflected in communities having a fairly even distribution among all four groups, and with substantial representation in the sensitive EPT groups. A sample with a disproportionate number of the generally tolerant Chironomidae would indicate environmental stress. Factors limiting the presence and abundance of the sensitive EPT groups could include such things as sediment input, changes in water chemistry, flow, and temperature.

As the value for EPT / Chironomidae approaches or drops below 1.0 then the sample area is in a less then favorable condition.

The **Dominance Percent** is the ratio of individuals in the most abundant taxon to the total number of organisms identified. A sample dominated by relatively few taxa would indicate environmental stress, as would a sample composed of several taxa but numerically dominated by only one or two. Rather an abundance of taxa with a fairly equal distribution of individuals within the taxa is indicative of community balance.

The following table will help describe the health of the stream when using Percent Contribution of the Dominant taxa (EPA 444/4-89-001):

	Good	Average	Poor
% Contribution of Dominant Taxa	< 20 %	21 - 40 %	> 41 %

The **Percent Chrionomidae** is a metric that is sensitive to degraded conditions in the stream. Chironomidae as a group are more tolerant to pollution than other invertebrates. The lower the percent the better the condition.

The **Percent EPT** is also an index that is sensitive to degraded conditions in the streams. As a group, EPT are sensitive to negative changes in the stream. The higher the percent, the better the conditions for Salmonids.

The **EPT richness** index enumerates the number of genuses in the EPT group in the sample. Since this group is generally sensitive to degraded conditions, a larger number indicates better conditions in the stream.

Biotic Index

The **Hilsenhoff Index** is a biotic index. This index weights the relative abundance of each taxon in terms of its pollution tolerance to determining a community score. Generally the higher the score the poorer the water quality (Hilsenhoff, 1982). It is not clear if this index has been adequately calibrated for the North Coast, but it will still be useful for monitoring change.

Index	Condition
0.85 to 1.75	Excellent
1.76 to 2.25	Very Good
2.26 to 2.75	Good
2.76 to 3.50	Fair
3.51 to 4.25	Poor
4.26 +	Very Poor

Functional Feeding Groups

These metrics try to measure how changing stream conditions change the food supply thus favoring one type of feeder over another.

The **percent scrapers** is a metric that is sensitive to toxicants and modification of the riparian zone (Rosenberg and Resh, 1993). Generally, the lower the percentage the cooler the water and the denser the canopy (Resh 1996 Per. Com.).

FINE SEDIMENTS

As part of the monitoring program, stream sediments have been measured across the property and in the region by PL and F&G. There have been 368 sediment samples collected, mostly during the last four years, using McNeil and Shovel samplers. Nearly all of the samples were analyzed by F&G. In 1996 we deleted 238 F&G sediment samples from the database on the advise of F&G. It was decided by F&G that by sampling the exact same spot each year and not the best spawning gravels in riffles, they had introduced a bias into the study. We threw out all but the first year's data.

In 1995 the California Dept. Of Fish and Game (Hopalin, pers. Com. 1996) did a comparison of McNeil and Shovel sampling methods. In 8 comparison reaches, the average percent fines <0.85 was 18.7% for McNeil samples and 21.0% for shovel samples. A study in Washington (Schuell-Hames, 1996) concluded there were no statistically significant differences in mean percent fine sediments (<0.85).

The percent fine sediment (< 0.85mm) is commonly believed to affect the ability of fish to spawn successfully. It has been reported that salmonid survival begins to decline when fines exceed 20% (Lisle and Eads, 1991). The exact relationship is not fully understood.

There is a high degree of variability within monitoring stations, within streams, between streams and between years.

It is interesting to look at streams that have had almost no logging or other post European impacts. The three reference streams in Humboldt Redwood State park average 20.8% fines. Godwood Creek measured in the late 1960's (Burns, 1970) had 17.6% fines. And, South Fork Yager Creek also measured by Burns in the late 1960's prior to any harvesting had 18.6% fines.

By contrast, the Yager basin with 127 samples over 15 years has an average of 17.6% fines. Freshwater Creek, with 24.2% fines, has been recovering from extensive logging around the turn of the century and is generally considered to be a healthy Coho Fishery.

It may well be that natural fine sediment levels of greater than 20% are common and normal in our north coast streams. It may also be that the impact of logging on sediment production may not be as great as is commonly believed.

It is also interesting that the high variability within streams would allow a discriminating salmonid to find good quality gravels in almost any stream in almost any year. There are only six instances out of 44 streams and years where sediments with less than 20% fines were unavailable. One of these is Bull Creek in the state park.

TEMPERATURE

We now have 79 good quality continuous temperature records in this area. The first good numbers were collected by F&G in 1991 using a "Temp. Mentor".

The effect of high temperature on salmonids is often expressed as the upper incipient lethal temperatures (ULIT). This is the temperature at which 50% of the exposed fish die (Fry, 1947). The ULIT for Chinook has been estimated at around 25°C (77°F) (Brett, 1955 and Orsi, 1971). There is some indication that fish in the southern end of the range may be able to tolerate higher temperatures (Orsi, 1971) than the study fish from British Columbia. There is also some indication that diurnal fluctuations in temperature help condition fish to withstand higher ULIT's

(Threader and Houston, 1983 and Health, 1963).

Fish are mobile, so on the few days each year when temperatures exceed ULIT, they probably move up the tributaries or take refuge in cool pools.

In general, the larger the watershed, the wider the channel, the warmer the water. This is perhaps due to the inability of the riparian vegetation to shade the water. It may also be a result of larger streams having a larger percent of their watersheds in upland prairie lands. In our smaller forested tributaries, peak water temperatures are generally between 60° and 70° F. Similar sized tributaries in Humboldt Redwoods state park were 63° and 67° F. In streams with good canopy cover, it may be that temperature has more to do with the size of the watershed than the type of cover.

A problem in streams like Yager is the temperature of the water we receive from upstream. These upland areas tend to be prairie lands with less shade producing riparian zone. As the water in the mainstem of Yager passes through our property it is cooled by the water from our forest lands. In 1992, the peak water temperature we received at the Straddle Legged bridge was 78°F on July 15. At the lower end of our property on that same day it was 71°F. This is probably due to the contribution of cool water from the smaller tributaries where we own most of the watershed and are able to maintain the shade canopy in the riparian zone.

STREAM BED SURVEYS

In 1996 PALCO began installing stream bed surveys. This is a technique that is being developed by Dr. Bill Trush and Simpson Timber Company. Using an engineer's level, a field crew carefully measures the bed of the stream under the thalweg moving up the stream. We measured 12 of our monitoring stations, surveying upstream for 500' to 1,000'. This gave us X (elevation) and Y (distance) coordinates. A linear regression of this data gives us the elevation, slope and coefficient of variation. The coefficient of variation should correlate to pools, structure and cover that are beneficial to fish. Subsequent remeasurement of the reaches should give us information about aggradation or degradation and the change in complexity.

LARGE WOODY DEBRIS SURVEYS

To address the levels of large woody debris (LWD) we will begin using the State of California's protocols to measure LWD. We will survey for LWD in the stream reaches where stream bed surveys are being conducted.

STREAM REACH MONITORING TECHNIQUES

1. Selecting Sites

- a. Semi random selection
 - i. 28 sites were selected semi randomly in 1994
 - (1) Henry Alden selected the sites soon after his arrival at the company with very little knowledge about the condition of particular streams.
 - (2) The site were selected on the map prior to any field visits
 - (3) The forester establishing the stations was trained in station layout but had very little training or knowledge in how to assess sites in terms of "good" or "bad".

b. Random Selection

- i. An additional 20 sites were randomly selected in 1995
- ii. A 500 acre GRID map with nodes was used to locate the new sites.
- iii. All nodes between 2,000 and 5,000 acres were numbered. Larger streams will be selected in a similar manner.
- iv. If a node is at the confluence of streams, up to three sites can be counted. You can go up or down each fork if they are in the proper range.
- v. Start a new sequence of numbers in each Watershed Assessment Area (WAA)
- vi. Allocate monitoring sites proportional to PL acreage in each WAA
 - (1) Humboldt Bay 15
 - (2) Yager 8
 - (3) Van Duzen 6
 - (4) Eel 18
 - (5) Bear River and Mattole 7
- vii. We used a random number generator to select sites
- viii. A selected site must meet the following criteria
 - (1) Located on PL land
 - (2) No randomly selected site can be within mile of another site
 - (3) If the stream dries out before the fall rains, it can not be used
 - (4) If the location of the GRID stream is different than the actual stream go upstream from the node until it hits the stream

c. Sites of interest

- i. Some sites have been selected because they are of special interest
 - (1) Reference streams have been selected for being pristine or highly disturbed.
 - (2) Cow Creek, Squaw Creek and Canoe Creek in the park were selected as undisturbed reference streams
 - (3) Cuneo Creek in the park was selected because it is highly disturbed
 - (4) A McCready Gulch site was selected because of the interest in the area.

2. Locate 200' Stream Reach

- a. Go to the ground location of the site
- b. If it is a straight stretch go upstream
- c. If the site is a confluence go up or down as appropriate (See 1.d.)
- 3. Characteristics of a suitable site
 - a. Straight
 - b. Identifiable bank to determine bank full discharge

- c. At least one pool and one riffle
- 4. Record Site
 - a. Place rebar at the bottom, middle and top of reach
 - b. Record pools, riffles and runs.
 - c. Reference marker on road and field directions
 - d. Watershed, Creek, T, R, Sec
- 5. Identify macroinvertebrate sampling riffle
 - a. Select riffle for sampling
 - b. Place rebar at start and end of riffle
 - c. Select four sample sites for ease of collection
 - d. Combine samples into one sample per site
 - e. Take temperature in riffle
 - f. Record upstream distance of each collection site
 - g. For remeasurements, try to remeasure the same riffle. If the riffle has moved, locate and measure another riffle as above.
- 6. Shovel sediment sample
 - a. Locate three sites at pool/riffle breaks (1996+)
 - i. Start at the down end of the reach, go upstream and sample the first three pool/riffle breaks. This may result in leaving the upstream reach.
 - ii. It is not necessary to mark the site
 - iii. Sample in thalweg
 - b. Collect shovel sediment samples
 - i. Do not combine samples
 - ii. Identify sample with flagging in and outside of garbage bag
 - c. For remeasurements, try to remeasure the same riffle. If the riffle has moved, locate and measure another riffle as above.
- 7. Do a pebble count as described in Chapter 11 of RM-425
 - a. Sample the riffle section identified for the insect collection
 - b. Sample transects across the stream
 - i. Start one step in from the bank full line
 - ii. Sample every step
 - iii. After last full step, go upstream one step
 - iv. Transects should be one step apart moving upstream
 - c. Tally each sample
 - d. For remeasurements, try to remeasure the same riffle. If the riffle has moved, locate and measure another riffle as above.
- 8. Temperature measurement
 - a. Place a Hobo where there is good water mixing and it is unlikely to go
 - b. Monitor temperature from June to October
- 9. Canopy Cover
 - a. Use a hemispherical mirror densiometer at 50', 100' and 150'
 - b. Collect four measurements at each point by facing N,S,E & W.
 - c. Average the four samples
- 10. Stream bed Survey
 - a. Frequency


- i. 1996 12 stations
- b. Methods
 - i. On a subset of the stations we conducted Stream bed surveys with an engineers level
 - ii. Set permanent benchmark out of the channel at the downstream end of the station
 - (1) Drive a railroad spike into the base of a tree at least 24" DBH
 - (2) 18" X 1" pipe with footing
 - (3) Map and flag the benchmark location
 - iii. Start point elevation at the benchmark is 100'
 - iv. The start point in the stream should be the downstream end of station
 - v. Lay a surveyors measuring tape along the channel as far as possible in a straight line
 - (1) Record the distance and bearing of the straight line
 - vi. Survey points at all grade changes in the bottom of the channel
 - (1) Measure at the thalweg
 - (2) Record elevation
 - (3) Record distance from the start point
 - (4) Record the offset from the tape line
 - vii. Measure 500' to 1000' up the stream
 - viii. Close the transect back to the start point to prevent major errors
- 11. Large Woody Debris (LWD) Survey
 - a. Frequency
 - i. 1997 26 stations
 - b. Methods
 - i. LWD surveys were done on reaches where streambed surveys were run
 - (1) Check map and notes in the WAA binders for station locations
 - (2) Check stream survey data for stream reach length
 - ii. Find the start point of the streambed survey and begin measurement of LWD
 - (1) Start of reach should be marked with flagging and orange painted rebar on both sides
 - iii. Measures LWD pieces upstream through entire length of streambed survey reach
 - iv. Use loggers tape to measure diameters and lengths until accurate estimates can made without measuring calibrate with the tape periodically as a check
 - v. Measure LWD pieces and record the required measurements on form check form for appropriate units (i.e., feet vs. inches) for each measurement:
 - (1) Record the **location** of each LWD piece relative to the bankfull channel (see figure):
 - (a) <u>Bankfull</u>, code 3: Any LWD piece which falls all or partially within the bankfull channel. Be sure to identify the location of bankfull channel as closely as possible by noting changes in sediment size, moss lines or scour lines on roots and rocks, and vegetation changes.
 - (b) <u>Centerline</u>, code 4: LWD which crosses the centerline of the bankfull channel
 - (c) <u>Left Bank</u>, code 2: LWD that does not enter bankfull channel, but lies entirely or partially within the top of the bank on the left side of the stream (facing downstream)


- (d) <u>Right Bank</u>, code 1: LWD that is oriented as described for left bank, but is on right side of channel facing downstream
- (2) LWD **Type**: For standing logs (live: code 4, or snags: code 2), estimate height to 6" top, and give DBH. For down/perched logs, code 1, 3, or 6: record the length and diameter at large end (D1) and small end (D2) (see figure)
- (3) Use the appropriate **Species** code use code 7 "other HW" for unidentifiable LWD species
- (4) Measure **Distance from 0** (start) of reach for each piece of LWS with fiberglass tape or stringbox
- (5) For **Rootwads**, code 5: measure diameter at the cut line as well as the A axis, B axis and C axis, and measure trunk sections attached to rootwads the same way as for logs (see figure)
- (6) The **Quality** index of the LWD refers to whether it is an intentionally placed object such as a cabled log, code 1 keyed in, log weir code 2, or log bridge, code 3. Only "placed" items need a code.


12. Tools


- a. 200' tape
- b. Rebar and hammer
- c. Thermometer
- d. Map
- e. Flagging and permanent marker
- f. Reference tag
- g. Paint
- h. Dip net (500 micron)
- i. Plastic pans
- j. Poly propylene jars
- k. Squirt bottle
- 1. Number 35 sieve
- m. Forceps
- n. Alcohol-proof pen
- o. Water proof paper
- p. California stream bioassessment procedures and worksheet
- q. Shovel
- r. Plastic bucket
- s. Garbage bags with ties
- t. Fish & Game field note form
- u. Metric Caliper
- v. Metric tape measure
- w. Cobble forms
- x. Concave hemispherical densiometer

Station #				Location	Code	Туре	Code	Species		Code
· lation #				Bank Full Center Line	3	Log Snag	2	Redwood		1 2
Station Na	ame	-		Left Bank	2	Perched	3	White W		3
Date				Right Bank	1	Live log up Rootwad	4 5	Alder		4 5
C				Qulaity	Code	Live log down	6	Willow		6
Crew				Keyed in Projects	2			Other HV	v	7
Total Leng	th			Bridges Etc.						
Locaton	Туре	Species	LV	VD Dimensio	ns	Distance	Ro	ot Wad S	ize	Qulaity
			Diameter 1	Diameter 2	Length	From 0'	A Axis	B Axis	C Axis	Quiant
			(Inches) Large End	(Inches) Small (8")	(Feet)	(Feet)	(Feet) (Height)	(Feet)	(Feet)	
							(Hoight)			
<u> </u>								-		
:										
				:						
				-						










A: LOCATION = 1 (BANKFULL)

TYPE = 2 (SNAG)

DIMENSIONS= 30° ×6" × 93'

B: LOCATION = 3 (LEFT BNUK)
TYPE = 2 (SNXE)
PMENSIONS = 25"X 18"XSS"



Date	Log CuFt	Root Wad	Total CuFt	Pieces
r Mattole \	WAA			
10/28/97	401.2	0.0	401.2	7.0
10/10/97	178.0	382.4	560.4	2.4
11/4/97	497.4	201.0	698.3	5.2
WAA				
8/7/97	107.8	0.0	107.8	0.7
10/24/97	60.7	54.8	115.4	1.3
8/12/97	121.0	8.5	129.6	1.4
8/5/97	212.9	36.9	249.8	3.3
10/3/97	415.5	166.8	582.4	5.6
8/6/97	642.7	153.7	796.4	0.8
10/6/97	841.7	165.9	1,007.6	13.9
10/23/97	1,063.1	124.2	1,187.4	3.3
10/17/97	1,418.5	127.9	1,546.4	5.7
) 10/10/97	1,669.8	108.8	1,778.6	3.0
10/23/97	1,311.3	667.3	1,978.6	17.4
nboldt WA	.A			
8/18/97	131.2	2.4	133.5	2.6
10/1/97	293.3	53.6	346.9	3.4
9/24/97	531.9	0.9	532.8	5.3
9/25/97	641.4	38.6	680.0	5.9
9/25/97	655.3	40.2	695.6	7.3
10/24/97	844.5	52.2	896.7	10.7
10/14/97	5,347.9	535.3	5,883.2	11.6
Duzen W	AΑ			
10/27/97	146.2	85.9	232.2	4.2
5/14/97	357.0	91.9	448.9	4.7
10/21/97	492.5	322.6	815.1	4.8
er WAA				
10/24/97	93.9	7.4	101.3	1.0
9/23/97	278.8	134.6	413.4	2.3
	10/28/97 10/10/97 11/4/97 WAA 8/7/97 10/24/97 8/12/97 8/5/97 10/3/97 10/6/97 10/6/97 10/23/97 10/17/97 10/10/97 10/23/97 10/1/97 9/25/97 10/1/97 9/25/97 10/24/97 10/24/97 10/27/97 5/14/97 10/21/97 er WAA	r Mattole WAA 10/28/97	r Mattole WAA 10/28/97	T Mattole WAA 10/28/97

Page 1 of 1

Friday, April 24, 1998

Stream Bed Surveys

?4-Apr-98

# Station	Planning Watershed	Date	Slope %	6 CV %	Length	Agradation or Degradation (Fe since last surve	et)
Bear Mattole	e WAA						
1 Bear River 1	Beer Bottle	8/8/97	1.1%	1.00%	1 .000		
13 1 Harmonica 1	Happy Valley	10/29/97	1.9%	0.81%	1.000		
134 Pullen 1	Happy Valley	11/3/97	3.0%	0.85%	1.000		
В	ear River Sub Watershed		2.0%	0.89%	1,000		
	Bear Mattole WAA		2.0%	0.89%	1.000		
Eel WAA							
4 Nanning 1	Dean Creek	10/3/97	2.1%	0.90%	1.000		
137 Cuneo	Fox Camp	10/31/96	7.7%	0.58%	477		Large landslides in park Has been logged
124 Howe 1	Howe Creek	8/6/97	1.9%	0.92%	736		Has been logged
2 Larabee 1	Larabee	8/15/97		2.35%	1.000		
115 Strongs 2	Newberg	8/5/97		1.16%	522		
107 Bear Cr 2	Pepper-wood	8/4/97		0.43%	1,000		
130 Shively 1	Pepperwood	8/7/97	1.1%	0.83%	570		
106 Monument 2	Scotia	10/9/96	2.7%	1.08%	800		
106 Monument 2	Scotia	9/30/97		1.03%	998	0.800	
122 Newman 1	White House	8/12/97	1.5%	0.87%	577		
	Eel Sub Watershed		2.4%	1.01%	768	0.800	
102 Squaw 1 (61% C	OG) Fox Camp	10/22/96	0.8%	0.94%	657		Virgin OG in Park
102 Squaw 1 (61%	OG) Fox Camp	10/7/97		0.71%	700	1.910	Virgin OG in Park
103 Canoe 1 (62%	OG) Myers Flat	10/21/96	1.6%	1.55%	976		Virgin OG in Park
103 Canoe 1 (62%	OG) Myers Flat	9/25/97		1.80%	950	0.190	Virgin OG in Park
105 cow 1 (93%	6 OG) Weott	10/23/96	2.1%	1.16%	644		Virgin OG in Park
105 c o w 1 (939	% OG) Weott	9/25/97		0.70%	607	1.030	Virgin OG in Park
]	Reference Sub Watershed		1.5%	1.14%	756	1.043	
	Eel WAA		2.1%	1.06%	763	0.982	
Humboldt W	/AA						
14 N Fk Elk R 1	Scout Camp		0.1%	0.92%	1,040		
14 N Fk Elk R 1 Sc	cout C a m p	9/25/97	0.1%	0.91%	1.040	0.160	
	Elk Sub Watershed		0.1%	0.92%	1,040	0.160	
18 Little Freshwat		9/20/97	0.9%	0.83%	997		
15 S Fk Freshwate		9/18/97	1.8%	2.23%	968		
135 McCready	Eddysville	10/30/96		1.10%	744		
35 McCready	Eddysville	9/25/97		1.44%	552	-0.380	
•	Freshwater Creek	10/10/96	0. 9%		805		

# Station	Planning Watershed	Date Slo	pe %	CV %	Length	Agradation or Degradation (Feet) since last survey	Comments
34 Freshwater 4	Freshwater Creek	9/25/97			870	- 0. 900	
19 Graham Gulch 1	Freshwater Creek	9/15/97	1.5%	0.62%	712		
Fre	shwater Sub Watershed	=	1.3%	1.23%	807	- 0. 640	
12 Salmon 1	Upper Salmon Creek	10/16/96	1.6%	1.20%	462		
12 Salmon 1	Upper Salmon Creek	10/14/97		1.20%	500	- 0. 580	
	Salmon Sub Watershed	Ξ	1.6%	1.20%	481	- 0. 580	
	Humboldt WAA	Ξ	1.0%	1.16%	790	- 0. 425	
VanDuzen W	AA	_					
108 Cummings 1	Cummings	11/11/97	3.7%	1.19%	1,000		
111 Grizzley 1	Grizzly Creek	10/20/97	1.5%	0.98%	1.000		Random
112 Hely 1	Hely Creek	10/18/96	0.2%	0.12%	490		
112 Hely 1	Hely Creek	9/25/97					
3 Root 1	Root Creek	10/27/97	1.1%	1.30%	753		
Va	n Duzen Sub Watershed	_	1.6%	0.90%	811		
	VanDuzen WAA	-	1.6%	0.90%	811		
Yager WAA							
5 Yager 1	Camp	10/14/96	1.1%	2.67%	1,067		
5 Yager 1	Camp	10/15/97			1.100	- 0. 900	
11 N Fk Yager 1	North Fork Yager Cre	10/11/96	0.8%	1.15%	1,000		
11 N Fk Yager 1	North Fork Yager Cre	9/25/97		1.01%	1,000	- 0. 740	
9 Lawrence 1	Side 8	9/19/97	0. 6%	1.08%	1,195		
	Yager Sub Watershed	- -	0. 8%	1.48%	1,072	- 0. 820	
	Yager WAA	-	0. 8%	1.48%	1,072	- 0. 820	
ALL WAA'S	Minimum	=	0.1%	0.12%	462	- 0. 900	
	Maximum		7 70/	2. 67%	1,195	1.910	
	Maximum		7. 770	2.07/0	1,173	1.910	

Stream Assessments

Planning Watershed: Eddysville

24-Apr-98

All (Mad to Mattole) Watershed Assessment Area
PALCO Ownership

Hydrologic Unit Planning Watershed Creek	PNMCD # \	Year	Total ⁹ Feet	% Pools	Pools per Mile	Backwater Pools per Mile	Mean Pool Depth	Maximum Pool Depth	Residual Pool Volume	Canopy Cover %	Embedded- ness
Hydrologic Unit: Elk R	iver										
Planning Watershed:	Elkhead										
SF Elk River	V6033228	1994	3, 865	31%	64. 2	8. 2	0.89	1.73	213	86. 5%	2. 45
Elkhead	155 l	Units	3, 865	31%	64. 2	8. 2	0.89	1.73	213	86.5%	2. 45
Planning Watershed:	Scout Camp										
BRIDGE CREEK	V6003849	1990	1.926	43%	68. 5	24. 7	1.52	2.30	410	73.4%	2.69
MCWHINNEY CREEK	V6020792	1990	781	79%	135. 2	54.1	1. 20	1.72	556	82.8%	1.94
N.FRK.ELK R.	V6032061	1990	1,924	27%	54.9	0.0	1.54	2. 71	618	75.4%	3. 00
S.BRANCH N.FORK EL	V6033103	1990	7.497	40%	114. 8	29.6	1.08	1. 78	180	60. 8%	2.19
Scout Camp	507	Units	12,128	41%	99.3	25. 7	1.18	1.91	277	65.2%	2.29
Planning Watershed:	Turkey Foot										
Doe Creek	V6009264	1994	3 . 1 3	2 18%	65. 7	8.4	1.03	1.82	105	92.6%	2.88
Little NF Elk	V6018653	1994	1,790	24%	91. 4	8. 8	0.98	1.78	7 9	94.1%	3. 16
N. BRANCH N. FORK E	V6032040	1990	3,596	56%	114. 5	16. 2	1. 23	1.92	352	82.4%	2.49
Turkev Foot	373 (Jnits	8.518	35%	91.7	11.8	1.13	1.86	230	88.6%	2.73
Elk River	1,035	Jnits	24,511	37%	91.1	18.1	1.13	1.88	253	76.8%	2.46
Hydrologic Unit: Fresh	water Cr										
Planning Watershed:	Camp 12										
Little Freshwater Creek	V6018508	1994	6,302	56%	65.4	1.7	1.06	2.02	563	86.4%	2.46
SOUTH FORK FRESHW	V6033234	1994	11,734	38%	82.3	3.6	0.86	1. 76	184	96.5%	2. 05
Graham Gulch	V830233453	1993	104		0.0	50.8				88.6%	4. 00
Camp 12	603	Units	18,140	44%	76.0	3.2	0.92	1.84	298	93.5%	2.18

1

Hydrologic Unit Planning Watershed Creek	PNMCD # Year	Total % Feet	6 Pools	Pools per Mile	Backwater Pools per Mile	Mean Poo Depth	Maximum Pool Depth	Residual Pool Volume	Canopy Cover %	Embedded- ness
McCready Gulch	V830233456 1994	3, 470	45%	108. 0	0.0	0. 69	1.61	136	95. 9%	2.32
Eddysville	159 Units	3, 470	45%	108. 0	0.0	0. 69	1. 61	136	95.9%	2.32
Planning Watershed	d: Freshwater Creek	(
Graham Gulch	V830233453 1993	5. 574	24%	49. 3	2.8	0.97	2. 03	195	89. 3%	3. 28
Freshwater Creek	134 Units	5, 574	24%	49. 3	2.8	0. 97	2. 03	195	89. 3%	3. 28
Freshwater Cr	896 Units	27,184	40%	74. 6	2.7	0.88	1. 82	254	93.3%	2. 34
Humboldt WAA	1,931 Units	51,695	39%	82. 4	10.0	1.01	1. 85	254	84.5%	2. 41
Hydrologic Unit: Law	rence Cr									
Planning Watershed	d: Bell Creek									
LAWRENCE CREEK, U	V18010105013 1991	5, 573	32%	20.8	0.0	1. 75	3. 59	2295	48. 2%	2.04
BELL CREEK	V6030327 1991	3,996	26%	34. 4	1.3	1. 60	3. 01	638	68. 5%	2. 77
Bell Creek	125 Units	9,569	29%	26. 5	0.6	1.67	3. 28	1398	58.6%	2. 43
Planning Watershed	d: Booths Run									
LAWRENCE CREEK, U	V18010105013 1991	16.908	12%	11. 2	0.6	2.41	4. 25	2246	37.4%	2.86
BOOTHS RUN	V6030429 1 9 9 1	9,661	15%	21. 3	0.0	1.34	2.60	488	39. 5%	2. 49
FISH CREEK	V6031090 1 9 9 1	5, 626	34%	70. 4	4.7	0. 98	1. 73	141	72.9%	2. 06
Booths Run	517 Units	32.195	17%	24. 6	1.1	1.42	2. 56	736	48. 8%	2. 37
Planning Watershed	d: Lawrence Creek									
LAWRENCE CREEK, U	V18010105013 1991	4,995	45%	35. 9	1.1	1. 32	2.52	1403	50.0 %	2. 26
Lawrence Creek	73 Units	4,995	45%	35. 9	1.1	1. 32	2. 52	1403	50.0%	2. 26
Planning Watershed	d: Shaw Creek									
SHAW CREEK	V6032604 1993	16,325	27%	51. 1	1.3	1. 16	2.24	300	64.1%	2. 82
Shaw Creek	448 Units	16,325	27%	51.1	1.3	1. 16	2. 24	300	84. 1%	2. 82
Planning Watershed	l: Side 8									
LAWRENCE CREEK, U	V18010105013 1991	25.105	16%	7.8	0.0	2.46	4. 54	5049	33.8%	2.51

Hydrologic Unit Planning Watershed Creek	PNMCD#	Year	Total Feet	% Pools	Pools per Mile	Backwater Pools per Mile	Mean Pool Depth	Maximum Pool Depth	Residual Pool Volume	Cover %	Embedded- ness
CORNER CREEK	V6007395	1991	2,339	11%	27.1	0.0	1.10	2.08	140	89.2%	2.92
SHAW CREEK	V6032604	1993	43		0.0	736.7				85.0%	2.83
Side 8	280	280 Units	27,487	15%	9.4	1.2	2.13	3.94	3847	47.7%	2.64
Lawrence Cr	1,443 Units	Units	90.571	21%	25.6	1.1	1.42	2.68	1051	60.5%	2.56
Hydrologic Unit: Middle Yager	le Yager										
Planning Watershed: Bald Jessie	I: Bald Jessie		[
YAGER CREEK	V18010105010	1991	28		0.0	0.0				%0.06	
YAGER CREEK, S.F.	V18010105011	1991	6.631	16%	23.9	3.2	1.68	3.01	674	37.8%	2.96
YAGER CREEK, N.F.	V18010105012	1991	70		0.0	75.4				25.0%	2.00
Bald Jessie	130	130 Units	6,765	16%	23.4	3.9	1.68	3.01	674	37.7%	2.93
Planning Watershed: Humphrey	I: Humphrey										
YAGER CREEK, M.F.	V6031888	1991	2,768	22%	38.2	0.0	1.16	2.02	189	43.5%	2.30
Humphrev	48	48 Units	2,768	22%	38.2	0.0	1.16	2.02	189	43.5%	2.30
Middle Yader	178	178 Units	9.533	18%	27.7	2.8	1.47	2.62	480	39.2%	2.67
Hydrologic Unit: North Yager	h Yager										
Planning Watershed: North Fork Yager Creek	1: North Fork	Yager	Creek	I							
YAGER CREEK, N.F.	V18010105012	1991	14,011	20%	12.1	0.4	2.52	5.13	4821	20.4%	2.84
North Fork Yager Creek		132 Units	14,011	20%	12.1	0.4	2.52	5.13	4821	20.4%	2.84
North Yager		132 Units	14,011	20%	12.1	0.4	2.52	5.13	4821	20.4%	2.84
Hydrologic Unit: Lower Yager	er Yager										
Planning Watershed: Camp	d: Camp			I							
YAGER CREEK	V18010105010	1991	24,683	23%	11.6	0.0	3.34	5.54	10320	9.5%	2.92
COOPER MILL CREEK	V6007296	1990	7,509	36%	71.7	3.5	0.99	1.74	217	42.2%	1.95
Camp	465	465 Units	32,192	76%	25.6	0.8	1.80	3.06	3715	29.2%	2.21
Planning Watershed: Yager Creek	: Yager Creek			II.							

Hydrologic Unit Planning Watershed Creek	PNMCD # Year	Total % Feet	6 Pools	Pools per Mile	Backwater Pools per Mile	Mean Pool Depth	Maximum Pool Depth	Residual Pool Volume	Canopy Cover %	Embedded- ness
YAGERCREEK	V18010105010 1991	33, 250	20%	9.7	0. 2	2.17	4. 38	6386	15.6%	3. 26
YAGER CREEK, N.F.	V18010105012 1 9 9 1	5. 786	8%	5. 5	0.0	2.90	5. 10	5431	18. 4%	3. 17
LAWRENCE CREEK, U	V18010105013 1991	238	35%	44. 4	643. 4	4. 25	5. 15	2009	53.9%	3.13
BLANTON CREEK	V6003105 1 9 9 1	4.195	21%	52.9	8. 8	1. 32	2. 34	201	66. 1%	2. 11
YAGER CREEK, M.F.	V6031888 1991	171	6 %	30.9	30.9	0.70	1.90	3 9	31.4%	2.00
STRAWBERRY CREEK	V830236239 1991	3, 818	23%	76. 1	5. 5	0. 82	1.31	81	82.4%	2. 53
Yager Creek	630 Units	47, 458	19%	18. 6	4. 7	1. 55	2.87	2629	42. 7%	2. 77
Lower Yager	1,095 Units	79,650	22%	21.4	3. 1	1.68	2. 96	3153	37.0%	2.48
Yager WAA	2,848 Units	193,765	21%	23. 0	2. 0	1.57	2.87	1964	48. 2%	2.54
Planning Watershed CUMMINGS CREEK		18,688	- 9 %	16.7	0.0	1. 02	1.92	248	78. 5%	2. 51
Cummings	169 Units	18,688	9%	16. 7	0. 0	1. 02	1. 92	248	78. 5%	2. 51
Planning Watershed	d: Grizzly Creek									
GRIZZLY CREEK	V6031265 1991	10,471	21%	29.8	0. 5	1.53	2. 61	873	52. 3%	2. 53
Grizzly Creek	194 Units	10,471	21%	29.8	0. 5	1.53	2.61	873	52.3%	2. 53
Planning Watershed	d: Hely Creek									
HELY CREEK	V6014493 1991	7, 582	16%	37.6	2.1	0. 98	1. 92	120	90. 5%	2. 35
Hely Creek	173 Units	7, 582	16%	37.6	2.1	0.98	1.92	120	90.5%	2. 35
Planning Watershed	d: Hydesville									
YAGERCREEK	V18010105010 1991	3, 641	13%	2.9	0.0	2.75	5.95	6134	10.0%	4. 00
Hydesville	13 Units	3,641	13%	2.9	0.0	2.75	5.95	6134	10.0%	4. 00
Planning Watershed	: Root Creek			-			-			
ROOT CREEK	V6027412 1991	13,824	25%	39.3	2. 3	1.17	2.37	409	78.8%	2. 86
Root Creek	269 Units	13,824	25%	39. 3	2. 3	1. 17	2. 37	409	78.8%	2.86

Hydrologic Unit Planning Watershed Creek	PNMCD # Year	Total Feet	% Pools	Pools per Mile	Backwater Pools per Mile	Mean Pool Depth	Maximum Pool Depth	Residual Pool Volume	Canopy Cover %	Embedded- ness
Planning Watershed	d: Stevens Creek									
GRIZZLY CREEK	V6031265 1991	1,394	7 %	11.4	0.0	1.13	2. 13	267	49.5%	1.67
STEVENSCREEK	V6034080 1991	5, 063	27%	54. 2	6. 3	1.09	2. 23	262	67.4%	1.58
Stevens Creek	131 Units	6, 457	23%	45.0	4.9	1.09	2. 22	263	65.5%	1.59
VanDuzen WAA	949 Units	60, 663	17%	28.9	1.4	1. 17	2. 25	426	72.7%	2.45
VanDuzen WAA	949 Units	60, 663	17%	28.9	1.4	1. 17	2. 25	426	72.7%	2.45
Hydrologic Unit: Eel [Delta									
Planning Watershed	d: Dean Creek									
Dean Creek	V6008583 1992	1,612	33%	101.5	19.7	0. 57	1. 25	67	95.1%	3. 08
NANNING CREEK	V830236268 1992	7, 600	25%	54.9	3. 5	0. 86	1. 57	105	71.7%	3. 20
Dean Creek	284 Units	9.212	27%	63. 0	6. 3	0. 78	1.48	94	78.0%	3. 17
Planning Watershed	d: Newberg									
N.F. STRONGS CREEK	V6023210 1993	5, 742	57%	78. 2	2.8	1. 29	2.43	372	93.9%	3. 70
Newberg	158 Units	5, 742	57%	78. 2	2.8	1.29	2.43	372	93.9%	3. 70
Eel Delta	442 Units	14,964	38%	68.9	4.9	1.00	1.90	215	83.7%	3. 41
Hydrologic Unit: Lara	bee Cr									
Planning Watershed	d: Boulder									
LARABEE CREEK	V18010105008 1992	2,970	33%	17.8	0.0	1. 31	3.03	2461	9.4%	2. 40
Boulder	26 Units	2.970	33%	17.8	0.0	1.31	3.03	2461	9.4%	2. 40
Planning Watershed	d: Larabee									
LARABEE CREEK	V18010105008 1992	44,529	29%	15.4	0. 2	1.82	3.87	4422	9. 2%	2. 09
Arnold Creek	V6000877 1992	1,248	15%	33.8	0.0	0.94	1.51	79	99. 4%	2. 88
BALCOM CREEK	V6001233 1992	1, 787	4 9 %	168. 4	20.7	1. 03	1. 63	65	96.6%	3. 71
CARSON CREEK	V6005466 1992	4, 846	25%	75. 2	5. 4	0. 78	1. 49	59	83. 8%	2. 80
Scott Creek	V6028804 1992	1, 320	37%	68. 0	4.0	1. 20	1.91	315	90.7%	2. 86

Hydrologic Unit Planning Watershed Creek	PNMCD # Year	Total Feet	% Pools	Pools per Mile	Backwater Pools per Mile	Mean Pool Depth	Maximum Pool Depth	Residual Pool Volume	Canopy Cover %	Embedded- ness
Larabee	696 Units	53, 730	29%	27.6	1. 5	1. 34	2. 64	2095	54.2%	2. 66
Larabee Cr	722 Units	56, 700	30%	27.1	1.4	1. 34	2. 66	2107	52.6%	2. 65
Hydrologic Unit: Lower	Eel									
Planning Watershed:	Pepperwood									
BEAR CREEK	V6001770 1991	15, 918	21%	37.8	1. 3	1. 45	2. 42	380	64. 5%	2. 34
DARNELL CREEK	V6008345 1992	1, 016	26%	78. 0	0.0	0. 99	1. 94	99	78.8%	4. 00
GREENLAW CREEK	V6013398 1991	3, 515	20%	67.6	4.5	0. 78	1. 38	70	77. 9%	2. 66
SHIVELY CREEK	V6029405 1992	8, 185	35%	29.7	3.9	0. 75	1. 90	209	67.9%	2. 80
Pepperwood	574 Units	26.634	25%	40.6	2.4	1. 14	2. 06	262	60.¥1.	2.61
Planning Watershed:	Red Crest									
Allen Creek	V60004111 9 9 2	1, 898	14%	50. 1	0.0	0.77	1. 48	57	98. 7%	1.44
CHADD CREEK	V6005946 1 9 9 2	10.854	22%	44.8	0.5	0. 96	1. 61	155	86. 3%	2.49
WEBER CREEK	V6037768 1992	2, 215	10%	38. 1	2.4	0. 68	1. 43	45	52.4%	2. 76
Red Crest	513 Units	14,966	19%	44. 5	0.7	0.89	1.57	127	83.0%	2.37
Planning Watershed:	Scotia									
Monument Creek	V6021843 1 9 9 3	5, 313	14%	20.9	0.0	0. 96	2. 04	279	81.0%	3. 38
Scotia	96 Units	5, 313	14%	20.9	0.0	0.96	2. 04	279	61.0%	3. 38
Planning Watershed:	Stafford									
DINNER CREEK	V6009152 1990	4, 961	27%	60.7	14.9	0. 72	1. 05	59	63.6%	3.57
JORDAN CREEK	V6016720 1991	7,955	15%	25.9	1.3	0.96	2. 11	153	74.8%	1. 82
KILER CREEK	V6017172 1990	4, 080	23%	68.6	9.1	0. 80	1. 18	61	51.8%	3.34
TWIN CREEK	V6036515 1990	5,899	25%	51.9	1.8	0. 94	1. 50	129	46. 5%	3. 30
STITZ CREEK	V830236274 1992	1,982	24%	55. 9	2.7	1.04	2. 20	210	81.6%	3. 19
Stafford	760 Units	24, 676	22%	46. 4	5. 5	0. 86	1.48	107	61. 2%	3.09
Lower Eel	1,943 Units	73,769	22%	42.6	2.9	0.97	1.73	174	70.1%	2.77

Hydrologic Unit Planning Watershed Creek	PNMCD # Year	Total Feet	% Pools	Pools per Mile	Backwater Pools per Mile	Mean Pool Depth	Maximum Pool Depth	Residual Pool Volume	Canopy Cover %	Embedded- ness
Hydrologic Unit: Sequ	uoia									
Planning Watershed	d: Line Gulch									
DOBBYN CREEK	V18010105007 199 5	1.146	48%	27.6	0.0	2.27	4. 75	3571	38.2%	2. 33
Line Gulch	11 Units	1,146	46%	27. 6	0.0	2.27	4. 75	3571	38. 2%	2.33
Planning Watershed	d: Lower South Do	bbyn Cr								
SOUTH DOBBYN CREI	E VPVA94021501 199 5	5 1,054	27%	10.0	0.0	1.50	4. 05	3781	7. 5%	3.00
Lower South Dobbyn C	re 8 Units	1,054	27%	10.0	0.0	1.50	4. 05	3781	7. 5%	3. 00
Planning Watershed	d: McCann									
THOMPSON CREEK	V6035661 1992	6,893	15%	46. 0	3. 1	1.10	1.74	124	50.9%	1. 83
UNNAMED TRIB OFF T	V830236728 1992	2,889	8 %	32.9	0.0	0.82	1.38	46	77.8%	2. 06
McCann	371 Units	9.762	13%	42.1	2.2	1. 03	1.65	106	56.1%	1.89
Planning Watershed	d: North Dobbyn C	reek								
SOUTH DOBBYN CREE	VPVA94021501 1995	2,503	23%	12.7	0.0	2.43	4.80	4478	10.8%	2. 75
North Dobbvn Creek	18 Units	2.503	23%	12.7	0.0	2.43	4.80	4478	10.8%	2.75
Planning Watershed	d: White House									
KAPPLE	V6016879 1 9 9 2	3,683	11%	41.6	0.0	0.80	1.42	36	63.3%	3.36
THOMPSON CREEK	V60356611992	73		0.0	217. 0				31.5%	3. 00
White House	146 Units	3,756	11%	40.6	4.2	0.80	1.42	36	61.1%	3.32
Sequoia	554 Units	18,240	17%	35.0	2.0	1.12	1.95	538	56.2%	2.35
Eel WAA	3,661 Units	163,663	26%	38.6	2.5	1.08	2.01	686	66.2%	2.81
Hydrologic Unit: Bear	River									
Planning Watershed	d: Beer Bottle									
BEER BOTTLE CREEK	V6002090 1996	1, 044	28%	75.9	0.0	0.26	2.07	0	36.8%	1.73
BEAR RIVER TRIB D	V830237877 199 6	1,075	39%	137. 5	19. 6	0.30	1. 70	40	32.9%	2. 78
Beer Bottle	101 Units	2,119	34%	107.1	10.0	0.28	1.83	26	34.3%	2.45

Hydrologic Unit Planning Watershed Creek	PNMCD # Year	Total Feet	% Pools	Pools per Mile	Backwater Pools per Mile	Mean Pool Depth	Maximum Pool Depth		Canopy Cover %	Embedded- ness
Planning Watershed	: Peaked Creek									
PEAKEDCREEK	V830237876 1996	5,255	25%	66.3	0.0	0.17	1.85	26	25.9%	2.60
Peaked Creek	146 Units	5.255	25%	66.3	0.0	0.17	1.65	26	25.9%	2.60
Bear River	247 Units	7,374	27%	76.0	2.9	0.21	1.84	26	29.3%	2.54
Hydrologic Unit: Uppe	r NF Mattole									
Planning Watershed	: Rattlesnake Cree	ek								
RATTLESNAKECREEK	V6026268 1991	22,138	16%	28.1	1.0	1.40	2.61	377	16.5%	2.94
Rattlesnake Creek	365 Units	22,136	16%	28.1	1.0	1.40	2.61	377	16.5%	2.94
Planning Watershed	: Tent City									
DEVILS CREEK	V6008934 1991	805	24%	26.2	0.0	1.02	2.03	105	22.5%	3.00
OIL CREEK	V6023613 1991	8,996	11%	20.5	2.9	1.03	1.87	246	12.0%	3.00
GREEN RIDGE CREEK	V830238020 1991	3,710	10%	19.9	0.0	0.97	1.71	273	29.7%	2.91
Tent Citv	205 Units	13.511	11%	20.7	2.0	1.01	1.64	242	15.5%	2.96
Upper NF Mattole	570 Units	35,649	14%	25.3	1.3	1.28	2.37	335	16.1%	2.95
Bear Mattole WAA	817 Units	43,023	16%	34.4	1.6	0.66	2.16	215	20.1%	2.78
All (Mad to Mattole)	10,206 Units	512,626	23%	35.7	2.6	1.17	2.22	634	61.5%	2.60

Stream Monitoring

All (Mad to Mattole) Watershed Assessment Area

24-Apr-98

	Year			Fine			Macı	roinverte	brates		ΑT				Temp.
d #		D84 +	D50 +	Sediment - <0.85 <4.7	CV% +	CuFt/ 100	Richness †	Simpson †	Hilsenhoff	С	F	Avg. C	Hig F	jh C	F
River															
d: Elkhe	ad		-												
13	1994	105	46				34	0.94	0.67						
13	1995	153	60				28	0.93	1. 01						
13	1996	149	63	19.3% 28.5%	6		29	0.93	1.05						
13	1997	102	50				33	0.94	1.27						
13		127	55	19.3% 28.5%	6		31	0.94	1.00						
23	1994	410	96	28.1% 39.6%	6		32	0.94	0.88						
23	1995	385	92				28	0.92	0.98					14.5	58.2
23	1996	348	54	21.6% 30.6%	6		37	0.95	0.94						
23	1997	174	55				44	0.94	1.38						
23		329	74	24.8% 35.1%	6		35	0.94	1.04					14.5	58.2
67	1994									14.3	57.7	14.9	58.9	15.1	59.2
67	1995													16.0	60.9
67	1996									14.7	58.5	15.9	60.7	16.5	61.7
87										14.5	58.1	15.4	59.8	15.9	60.6
	11 Units	228	85	23.0% 32.9%	6		33	0.94	1.02	14.5	58.1	15.4	59.8	15.5	60.0
d: Scout	t Camp														
14	1994	15	7	37.7% 62.6%	6		21	0.79	2.15					22.7	72.8
		15	8				18	0.64	1.86					19.5	67.1
14	1996	18	10	34.0% 60.1%	6 0.9%		18	0.78	1.97	17.8	64.1	19.1	66.3	19.4	66.9
14	1997	23	15		0.9%	533	21	0.76	1.88						
14		18	10	35.8% 61.4%	6 0.9%	533	20	0.74	1.96	17.8	64.1	19.1	66.3	20.5	68.9
	4 Units	18	10	35.8% 61.4%	6 0.9%	533	20	0.74	1.96	17.8	64.1	19.1	66.3	20.5	68.9
d: Turke	y Foot														
90	1995													16.1	60.9
90	1996									14.9	58.8	15.8	60.5	16.2	61.2
90										14.9	58.8	15.8	60.5	16.1	61.1
91	1995													15.7	60.3
										440					
91	1996									14.8	58.5	16.0	60.7	16.3	61.3
	d # River d: Elkhe 13 13 13 13 23 23 23 23 67 67 67 87 d: Scou 14 14 14 14 14 14 14 14 14 14 14 19 90 90 90	River d: Elkhead 13	River d: Elkhead 13	River	d # D84 D50 Sediment - + + + + + + + + + + + + + + + + + +	CV%	Cival Care Civ	Civic Civic Civic Cupt Richness	D84 D50 Sediment - + + + + + + + + + + + + + + + + + +	River	River d: Elkhead Bay 1050 8 - 4.7 Sediment - 1 - 10.08 5 < 4.7 Cuff 100 + 10.00 + 1	River	d # D84 P50 Sediment - (0.85 < 4.7) CW F100 Richness Simpson Hilsenhoff H P100 C F Avg. C River d: Elkhead 13 1994 105 46 13 1995 153 60 34 0.94 0.67 28 0.93 1.05 1.01 1.01 1.01 1.01 1.01 1.01 1.01	River	March Marc

Hydrologic Unit Planning Watersho Station	Station ed #	Year	Cob D84 +		Fine Sediment - <0.85<4.7	Complexity CV% +	y LWD CuFt/ 100'		roinvertel Simpson		MW.	AT F	7 E Avg. C	ay Hig F		Temp. F
Turkey Foot		4 Units									14.8	58.7	15.9	60.6	16.1	60.9
Elk River		19 Units	158	46	28.1% 44.3%	6 0.9%	533	29	0.87	1.34	15.3	59.5	16.4	61.4	17.1	62.8
Hydrologic Unit: Fre	shwater	Cr														
Planning Watershe	ed: Camp	12														
S Fk Freshwater 1	15	1994	101	24	25.4% 50.5%	, 0		34	0.92	1.62						
S Fk Freshwater 1	15	1995	257	40		-		41	0.95	1.40						
S Fk Freshwater 1	15	1996		167	26.5% 45.4%	, 0		35	0.88	1.62						
S Fk Freshwater 1	15	1997	473	57		2.2%	696	34	0.91	1.45						
Station Average	15		277	72	25.9% 48.0%		696	36	0.92	1.52						
Little Freshwater 1	18	1996	86	44	39.4% 53.5%			29	0.84	2.03						
Little Freshwater 1	18	1997	70	39	001.70 00107	0.8%	347	36	0.86	1.69						
Station Average	18		78	42	39.4% 53.5%		347	33	0.85	1.86						
Freshwater 2	32	1994	780	71	23.6% 31.9%		• • • • • • • • • • • • • • • • • • • •	31	0.93	157						
Freshwater 2	32	1995	745	162	20.070 01.070	o .		31	0.89	1.94						
Freshwater 2	32	1996	330	67	13.1% 28.9%	,		32	0.87	1.83						
Freshwater 2	32	1997	125	24	,	•		27	0.88	1.95						
Station Averaae	32		495	81	18.4% 30.4%	, n		30	0.89	1.82						
Freshwater 3	33	1994	89	48	15.7% 25.4%			34	0.92	1.79						
Freshwater 3	33	1995	135	60	10.770 20.170	o .		27	0.91	1.90					17.2	63.0
Freshwater 3	33	1996	106	46	14.6% 28.4%	,		28	0.91	1.80	16.2	61 1	18.2	64.8	18.4	65.0
Freshwater 3	33	1997	96	38	1 11070 201170	,		30	0.89	1.94	. 0.2	• • • • • • • • • • • • • • • • • • • •		0 1.0		00.0
Station Average	33		107	48	15.2% 26.9%	,		30	0.91	1.85	16.2	61 . 1	18.2	64.8	17.8	64.0
S Fk Freshwater 2	37	1994	108	47	21.8% 34.9%			33	0.92	1.53	10.2	<u> </u>		0 110	1110	
S Fk Freshwater 2	37	1995	133	46	,	•		37	0.89	1.93					15.8	60.5
S Fk Freshwater 2	37	1996	144	52	24.6% 41.3%	, D		35	0.92	1.53					10.0	00.0
S Fk Freshwater 2	37	1997	91	44		-		39	0.91	1.48						
Station Average	37		119	47	23.2% 38.1%	, n		36	0.91	1.62					15.8	60.5
Camp 12	<u> </u>	18 Units	228	60	22.7% 37.8%		521	33	0.90	1.72	16.2	61.1	18.2	64.8	17.1	62.8
Planning Watershe	d: Eddy	sville								· -						
Clonev Gulch 1	92	1995													17.2	63.0
Clonev Gulch 1	92 92	1995									16.1	61.0	175	63.6	17.2	64.1
Station Average	92	1330									16.1		17.5	63.6	17.5	63.5
		1996	E2	26	40 40/ GG 00/	ú 1.1%		20	0.89	1 11	10.1	01.0	17.5	03.0	17.3	03.3
McCready	135 135	1996	53 44	26 15	48.1% 66.8%		907	29 25	0.89 0.87	1.44 1.57						
McCreadv	135	1997	44	15		1.4%	897	25	0.87	1.57						

Hydrologic Unit Planning Watersh Station	Station ed #	Year	Cok D84 +		Fine C Sediment - <0.85 <4.7	complexit CV% +	CuFt/		croinverteb Simpson I		MW C	AT F	7 C Avg. C		High _I h C	Temp. F
Station Average	135		49	21	48.1% 66.8%	1.3%	897	27	0.88	1.51						
Eddysville		4 Units	49	21	48.1% 66.8%	1.3%	897	27	0.88	1.51	16.1	61.0	17.5	63.6	17.5	63.5
Planning Watersh	ed: Fresh	water C	Creek													
Graham Gulch 1	19	1994	69	21	22.0% 37.0%			33	0.93	1.86						
Graham Gulch 1	19	1995	138	61				31	0.89	1.96					17.1	62.8
Graham Gulch 1	19	1996	102	27	29.2% 49.2%			28	0.86	2.22						
Graham Gulch 1	19	1997	65	20		0.6%	680	36	0.91	1.82						
Station Average	19		94	32	25.6% 43.1%	0.6%	680	32	0.90	1.97					17.1	62.8
Graham Gulch 2	20	1994	71	33	25.1% 40.0%			37	0.93	1.51						
Graham Gulch 2	20	1995	72	28				32	0.91	1.58						
Graham Gulch 2	20	1996	65	24	23.9% 47.8%			25	0.88	1.45						
Graham Gulch 2	20	1997	94	45				35	0.92	1.55						
Station Average	20		76	33	24.5% 43.9%			32	0.91	1.52						
Freshwater 4	34	1994	127	63	17.9% 27.5%			38	0.93	1.74						
Freshwater 4	34	1995	177	78				32	0.92	1.62					18.5	65.3
Freshwater 4	34	1996	56	24	20.1% 33.2%	1.2%		23	0.85	1.61						
Freshwater 4	34	1997	148	29				23	0.89	1.61						
Station Average	34		127	49	19.0% 30.3%	1.2%		29	0.90	1.65					18.5	65.3
Freshwater 5	35	1994	77	56	21.0% 34.1%			35	0.94	1.63						
Freshwater 5	35	1995	61	31				29	0.91	1.25						
Freshwater 5	35	1996	178	35	24.6% 49.0%			29	0.88	2.12						
Freshwater 5	35	1997	117	52				29	0.83	2.11						
Station Average	35		108	44	22.8% 41.6%			31	0.89	1.78						
Freshwater 6	36	1994	310	76	25.1% 50.8%			40	0.94	1.46						
Freshwater 6	36	1995	299	73				40	0.92	1.58					14.5	58.2
Freshwater 6	36	1996	265	48	23.4% 44.0%			30	0.91	1.63	14.3	57.7	15.8	60.5	16.6	61.8
Freshwater 6	36	1997	152	41			134	46	0.94	1.16						
Station Average	36		257	60	24.3% 47.4%		134	39	0.93	1.46	14.3	57.7	15.8	60.5	15.6	60.0
Freshwater Creek		20 Units	132	43	23.2% 41.3%	0.9%	407	33	0.90	1.67	14.3		15.8	60.5	16.7	62.0
Freshwater Cr		42 Units	169	50	24.2% 41 .0%	1.2%	551	32	0.90	1.69	15.5	59.9	17.2	63.0	17.0	62.6
Hydrologic Unit: Sa	lmon Cr															
Planning Watersh	ed: Uppe	r Salmo	n Cre	ek												
Salmon 1	12	1994	118	60	41.1% 54.7%			32	0.92	1.64						
Salmon 1	12	1995	185	56				34	0.90	1.05	14.0	57.3	14.7	58.4	15.4	59.8

Hydrologic Unit S Planning Watershed Station	Station #	Year	Cok D84 +		Fine Sediment - <0.85 <4.7	Complexity CV% +	LWD CuFt/ 100'		roinvertel Simpson I +		MW.	AT F	Avg.	ay Hig F		Temp. F
Salmon 1	12	1996	168	92	25.5% 33.2%	1.2%		29	0.91	1.67						
Salmon 1	12	1997	132	55		1.2%	5,883	34	0.89	1.67						
Station Average	12		151	66	33.3% 43.9%	ú 1.2%	5,883	32	0.91	1.51	14.0	57.3	14.7	58.4	15.4	59.8
Salmon 2	21	1994	157	82	17.7% 33.7%))		30	0.92	0.92						
Salmon 2	21	1995	160	93				30	0.87	0.74						
Salmon 2	21	1996	186	91	26.4% 44.2%)		27	0.80	0.76						
<u>Salmo</u> n 2	21	1997	175	77				31	0.89	1.15						
Station Average	21		170	86	22.1% 38.9%))		30	0.87	0.89						
Salmon 3	22	1994	42	16	42.9% 55.3%)		34	0.87	1.51						
Salmon 3	22	1995	140	52				32	0.87	2.00						
Salmon 3	22	1996	225	107	46.2% 60.9%)		31	0.91	1.82						
<u>Salmo</u> n 3	22	1997	134	64				40	0.92	1.91						
Station Average	22		135	60	44.6% 58.1%)		34	0.89	1.81						
Upper Salmon Creek		12 Units	152	70	33.3% 47.0%	1.2%	5,883	32	0.89	1.40	14.0	57.3	14.7	58.4	15.4	59.8
Salmon Cr		12 Units	152	70	33.3% 47.0%	1.2%	5,883	32	0.89	1.40	14.0	57.3	14.7	58.4	15.4	59.8
Humboldt WAA		73 Units	164	53	26.6% 42.7%	1.2%	1,310	32	0.89	1.57	15.2	59.4	16.5	61.6	17.0	62.6
Hydrologic Unit: Lawre	ence C	r														
Planning Watershed	: Bell C	Creek														
Bell 1	117	1995	95	53				34	0.89	1.52						
Bell 1	117	1996	107	59	20.8% 34.6%)		26	0.84	1.46	14.9	58.8	15.8	60.4	16.4	61.5
Bell 1	117	1997	86	42				32	0.90	1.89						
Station Average	117		96	51	20.8% 34.6%	•		31	0.88	1.62	14.9	58.8	15.8	60.4	16.4	61.5
Bell Creek		3 Units	96	51	20.8% 34.6%			31	0.88	1.62	14.9	58.8	15.8	60.4	16.4	61.5
Planning Watershed	: Booth	ns Run														
PL81	42	1980			5.0% 20.0%	1		17	0.73	1.60						
PL81	42	1981			6.0% 19.0%											
Station Average	42				5.5% 19.5%)		17	0.73	1.60						
Lawrence F&G 1	48	1991			10.3% 32.6%											
Lawrence F&G 1	48	1992													22.8	73.0
Lawrence F&G 1	48	1993													20.6	69.0
Lawrence F&G 1	48	1994						28	0.80	1.50					20.1	68.2
Station Average	48				10.3% 32.6%)		28	0.80	1.50					21.1	70.1
Booths Run	-	6 Units			7.1% 23.9%			23	0.77	1.55					21.1	70.1

Hydrologic Unit Planning Watershe Station	Station ed #	Year	Cok D84 +		Fin Sedime e0.85	ent -	Complexity CV% +	LWD CuFt/ 100'		roinverte Simpson +	ebrates Hilsenhoff	MW. C	AT F			High Jh C	Temp. F
Planning Watershe	d: Lawr	ence Cr	eek														
PL80	47	1980			12.0%	21.0%			11	0.61	1.39						
PL80	47	1981			14.0%	35.0%											
<u>PL80</u>	47	1995														17.6	63.8
PL80	47	1996										17.2	63.0	20.2	68.4	20.8	69.4
Station Average	47				13.0%	28.0%			11	0.61	1.39	17.2	63.0	20.2	68.4	19.2	66.6
Lawrence Creek		4 Units			13.0%	28.0%			11	0.61	1.39	17.2	63.0	20.2	68.4	19.2	66.6
Planning Watershe	d: Shaw	Creek															
Shaw F&G 1	38	1991			26.9%	39.8%											
Shaw F&G 1	38	1994							32	0.90	1.64						
Station Average	38				26.9%	39.8%			32	0.90	1.64						
Shaw F&G 2	39	1991			24.7%	45.1%											
Shaw F&G 2	39	1994							25	0.62	1.93						
Station Average	39				24.7%	45.1%			25	0.62	1.93						
Shaw F&G 3	40	1991			25.6%	40.1%											
<u>Shaw</u> F&G 3	40	1994							29	0.86	1.87						
<u>Shaw</u> F&G 3	40	1996			13.7%	30.0%						16.5	61.6	17.9	64.1	18.4	65.2
Station Average	40				19.7%	35.0%			29	0.86	1.87	16.5	61.6	17.9	64.1	18.4	65.2
PL40_	43	1980			9.0%	21.0%			13	0.68	1.23						
PL40_	43	1981			3.0%	16.2%											
Station Average	43				6.0%	18.6%			13	0.68	1.23						
Shaw Creek		9 Units			17.2%	32.0%			25	0.76	1.66	16.5	61.6	17.9	64.1	18.4	65.2
Planning Watershe	d: Side 8	В															
Lawrence 1	9	1994	290	160	23.9%	69.3%			35	0.91	1.76	18.5	65.3			21.0	69.7
Lawrence 1	9	1995	285	140					25	0.86	1.86						
Lawrence 1	9	1996	235	89	16.2%	39.2%			33	0.89	1.54						
Lawrence 1	9	1997	130	34			1.1%	413	29	0.89	1.83						
Station Average	9		235	106	20.1%	54.3%	1.1%	413	31	0.89	1.75	18.5	65.3			21.0	69.7
PL82_	44	1980				24.0%			8	0.65	1.47						
PL82	44	1981			11 .0%												
Station Average	44				10.0%				8	0.65	1.47						
Lawrence F&G 2	49	1991			16.4%	39.9%											
Lawrence F&G 2	49	1994			44.007	00 =01			24	0.82	1.68						
Lawrence F&G 2	49	1996			11.2%	33.5%											

Hydrologic Unit Planning Watersho Station	Station ed #	Year		l Fine 0 Sediment - - <0.85<4.7	Complex CV% +	city LWD CuFt/ 100'		croinverteb SImpson +		MW C	AT F		Day Hiç F		Temp. F
Station Average	49			13.8% 36.7	%		24	0.82	1.68						
Lawrence F&G 3	50	1991		15.1% 41.4	%										
Lawrence F&G 3	50	1994					32	0.79	1.57						
Station Average	50			15.1% 41.49	%		32	0.79	1.57						
Lawrence F&G 4	51	1991		9.0% 23.29	%										
Lawrence F&G 4	51	1994					34	0.88	1.78						
Station Average	51			9.0% 23.29	%		34	0.88	1.78						
Lawrence F&G 5	52	1991		21 .0% 44.29	%										
Lawrence F&G 5	52	1994					27	0.89	1.73						
Station Average	52			21 .0% 44.29	%		27	0.89	1.73						
Lawrence F&G 6	53	1991		15.5% 36.79	%										
Lawrence F&G 6	53	1992												22.2	72.0
Lawrence F&G 6	53	1994					25	0.76	1.50						
<u>Lawre</u> nce F&G 6	53	1996		10.9% 34.39	%										
Station Average	53			13.2% 35.59	%		25	0.76	1.50					22.2	72.0
Comer Cr	88	1995												14.7	58.5
Comer Cr	88	1996								14.5	58.1	15.3	59.6	15.6	60.1
Station Average	88									14.5	58.1	15.3	59.6	15.2	59.3
Side 8		21 Units	235 10	06 14.5% 37.69	% 1.1%	413	27	0.83	1.67	16.5	61.7	15.3	59.6	18.4	65.1
Lawrence Cr		43 Units	175 8	2 14.4% 33.49	% 1.1%	413	26	0.81	1.64	16.3	61.4	17.3	63.1	19.1	66.4
Hydrologic Unit: Mid	ldle Yage	er													
Planning Watershe	ed: Bald	Jessie													
S Fk Yaner 1	68	1967		16.4% 40.19	%										
S Fk Yaaer 1	68	1968		16.5% 39.99	%										
S Fk Yaaer 1	68	1969		23.6% 54.89	%										
S Fk Yaaer 1	68	1992													75.2
S Fk Yaaer 1	68	1995												20.3	68.6
Station Average	68			18.8% 44.9%										22.2	71.9
S Fk Yaner 2*	86	1967		16.4% 36.19											
S Fk Yaaer 2*	86	1968		17.3% 44.79											
S Fk Yaaer 2*	86	1969		22.1% 52.49											
Station Average	86			18.6% 44.49											
Bald Jessie		6 Units		18.7% 44.79	%									22.2	71.9

Hydrologic Unit Planning Watersh Station	Station ed #	Year		obel D50 +	Fine Sediment - <0.85 <4.7		cy LWD CuFt/ 100'		croinverte Simpson +		MW. C	AT F		Day Hiç F		Temp. F
Planning Watersho	ed: Hum _l	ohrey														
M Fk Yager 1	10	1994	178	57	18.7% 29.9	%		37	0.91	1.81						
M Fk Yager 1	10	1995	317	97				40	0.94	1.97						
<u>M Fk</u> Yaaerl	10	1996	218	84	21.2% 36.6	%		28	0.91	1.62						
<u>M Fk</u> Yaaerl	10	1997	174	46				32	0.92	1.69						
Station Average	10		222	71	20.0% 33.3	%		34	0.92	1.78						
Humphrey		4 Units	222	71	20.0% 33.3	%		34	0.92	1.78						
Middle Yager		12 Units	222	71	19.0% 41.8	%		34	0.92	1.78					22.2	71.9
Hydrologic Unit: No	rth Yage	r														
Planning Watershe	ed: North	Fork Y	ager	Cree	k											
N Fk Yager 1	11	1992													25.6	78.0
N Fk Yager 1	11	1994	300	90	21.2% 49.1	%		31	0.90	2.22						
<u> </u>	11	1995	335	129				27	0.92	2.06					28.8	83.8
<u>N Fk</u> Yaaerl	11	1996	235	54	17.8% 35.69			29	0.90	1.98					30.9	87.7
<u>N Ek</u> Yaaerl	11	1997	335	36		1.0%	101	31	0.88	1.81						
Station Average	11		301	77	19.5% 42.49	% 1.1%	101	30	0.90	2.02					28.4	83.1
<u>PL5</u>	45	1980			9.0% 28.09			14	0.80	1.80						
PL5	45	1981			10.0% 36.0											
Station Average	45				9.5% 32.0			14	0.80	1.80						
North Fork Yager Cree	ek	7 Units	301	77	14.5% 37.29	% 1. 1%	101	26	0.88	1.97					28.4	83.1
North Yager		7 Units	301	77	14.5% 37.29	% 1.1%	101	26	0.88	1.97					28.4	83.1
Hydrologic Unit: Lov	wer Yage	er														
Planning Watershe	ed: Camp)														
<u>Yane</u> rl	5	1994	265	-32	22.7% 42.29	%		27	0.87	2.12						
Yager 1	5	1995	889	298				24	0.85	2.05						
. <u>Yaae</u> rl	5	1996	450	52	18.8% 39.19	% 2.7%		23	0.82	1.83						
<u>Yager</u> 1	5	1997	481	54				24	0.84	2.17						
Station Average	5		521	109	20.7% 40.69	% 2.7%		25	0.84	2.04						
Cooper Mill 1	66	1992													19.4	67.0
Cooper Mill 1	66	1993													16.7	62.0
Cooper Mill1	66	1994									15.4	59.8	16.1	60.9	17.1	62.7
Cooper Mill1	66	1995												.	18.4	65.1
Cooper Mill 1	66	1996									14.9	58.7	16.4	61.5	16.9	62.4

Hydrologic Unit Planning Waters Station	Station hed #	Year		obel D50 +	Fine Sedime <0.85	nt -	Complexity CV% +	LWD CuFt/ 100'		Simpson		MW C	AT F	7 C Avg. C	ay Hig F	High _I h C	Temp. F
Station Average	66											15.1	59.2	16.2	61.2	17.7	63.8
Yaoer - at Camo	85	1992														23.9	75.0
Yaner - at Camp	85	1995														25.6	78.0
Station Average	85															24.7	76.5
Camp		11 Units	521	109	20.7%	40.6%	2.7%		25	0.84	2.04	15.1	59.2	16.2	61.2	19.7	67.5
Planning Watersh	ned: Yage	r Creek															
Yaner4	6	1994	99	14	16.0%	31.1%			31	0.90	2.02						
Yaner 4	6	1995	167	59					30	0.93	2.19						
Yager 4	6	1996	71	39	23.4%	46.5%			31	0.86	2.06						
Yaaer 4	6	1997	35	14					27	0.77	2.46						
Station Average	6		93	32	20.7%	38.8%			30	0.86	2.19						
Yaaer 3	7	1994	170	83	24.9%				33	0.89	2.22						
Yaaer 3	7	1995	187	46	,				22	0.89	2.11						
Yaaer 3	7	1996	168	58	18.7%	37.3%			28	0.91	2.04						
Yaner 3	7	1997	156	51					25	0.87	2.16						
Station Average	7		170	60	21.8%	38.8%			27	0.89	2.13						
Yaner 2	8	1994	76	16	20.0%	45.2%			25	0.91	2.16						
- Yaaer 2	8	1995	330	178					19	0.78	1.99						
Yaner 2	8	1996	365	246	22.3%	47.1%			23	0.92	2.04						
Yaner 2	8	1997	254	82					27	0.90	1.85						
Station Average	8		256	131	21.2%	46.2%			24	0.88	2.01						
PL22	46	1980			13.0%	24.0%			13	0.73	1.66						
PL22	46	1961			11.0%	22.0%			-								
Station Average	46				12.0%				13	0.73	1.66						
Yager Creek		14 Units	173	74	18.9%	36.7%			26	0.87	2.08						
Lower Yager		25 Units	260	83	19.3%	37.5%	2.7%		25	0.86	2.07	15.1	59.2	16.2	61.2	19.7	67.5
Yager WAA		87 Units	241	80	16.3%	36.1%	1.5%	257	27	0.85	1.84	16.0	60.8	16.9	62.5	20.8	69.4
Hvdroloaic Unit: Va Planning Watersh																	
Cumminas 1	108	1995	305	0.0					00	0.00	4.50						
Cumminas 1				83	OF 20/	44 40/			32	0.93	1.53	45.0	00.0	477	00.0	4	
	108 108	1996 1997	225	74 41	25.3%	44.4%	4.00/		31	0.92	1.46	15.6	60.0	17.7	63.8	17.9	64.3
Cumminas 1		1997	163		05.00/	44 407	1.2%		33	0.82	2.01	4					
Station Average	108		231	66	25.3%	44.4%	1.2%		32	0.89	1.67	15.6	60.0	17.7	83.8	17.9	64.3

Hydrologic Unit Planning Waters Station	Station hed #	Year		bel D50 +	Fine Sediment - <0.85 <4.7	Complexity CV% +	LWD CuFt/ 100'		croinvertek Simpson †		MW C	AT F	7 I Avg. C	Day Hiç F		Temp. F
Cummings		3 Units	231	66	25.3% 44.49	% 1.2%		32	0.89	1.67	15.6	60.0	17.7	63.8	17.9	64.3
Planning Watersh	ned: Grizz	ly Creel	K													
<u>Grizzle</u> v 1	111	1995	349	90				27	0.85	2.06						
<u>Grizzle</u> v 1	111	1996	326	116	23.9% 41.8%	6		24	0.87	1.98						
_ Grizzlev 1	111	1997	236	71		1.0%	815	31	0.90	1.72						
Station Average	111		304	92	23.9% 41.8%	6 1.0%	815	27	0.87	1.92						
Grizzly Creek		3 Units	304	92	23.9% 41.8%	6 1.0%	815	27	0.87	1.92						
Planning Watersh	ned: Hely	Creek														
Helv 1	112	1995	69	36				22	0.86	1.62						
Hely 1	112	1996	80	53	18.7% 29.5%	6 0.1%		19	0.82	2.13						
Helv 1	112	1997	65	28			449	21	0.89	1.98						
Station Average	112		71	39	16.7% 29.5%	6 0.1%	449	21	0.86	1.91						
Hely Creek		3 Units	71	39	16.7% 29.5%	6 0.1%	449	21	0.86	1.91						
Planning Watersh	ed: Root	Creek														
Root1	3	1994	50	27	35.1% 51.7%	6		19	0.84	1.64						
Root1	3	1995	52	31				27	0.86	1.59						
Root1	3	1996	125	81	24.4% 34.2%	6		24	0.84	1.63	15.3	59.5	16.3	61.3	16.5	61.8
Root 1	3	1997	87	43		1.3%	232	28	0.89	1.53						
Station Average	3		79	46	29.7% 42.9%	6 1.3%	232	25	0.86	1.59	15.3	59.5	16.3	61.3	16.5	61.8
Root2	109	1995	48	27				25	0.87	1.64						
Root2	109	1996	98	43	48.5% 58.6%	6		26	0.86	1.72						
Root2	109	1997	58	30				23	0.82	1.86						
Station Average	109		68	33	48.5% 58.6%	0		25	0.85	1.74						
Root Creek		7 Units	74	40	36.0% 48.2%	6 1.3%	232	25	0.85	1.66	15.3	59.5	16.3	61.3	16.5	61.8
VanDuzen WAA		16 Units	146	55	29.0% 43.4%	6 0.9%	499	26	0.87	1.76	15.4	59.7	17.0	62.5	17.2	63.0
VanDuzen WAA		16 Units	146	55	29.0% 43.4%	6 0.9%	499	26	0.87	1.76	15.4	59.7	17.0	62.5	17.2	63.0
Hydrologic Unit: Ee	el Delta															
Planning Watersh	ed: Dean	Creek														
Nanning 1	4	1994	225	24	40.6% 64.6%	6		30	0.89	1.89						
Nanning 1	4	1995	356	55				18	0.79	1.58					21.1	70.0
Nanning 1	4	1996	324	114	23.8% 40.8%			22	0.62	2.49						
Nanning 1	4	1997	162	16		0.9%	1.008	23	0.81	1.86						

Hydrologic Unit	Station	Year		bel	Fine	Complexity		Мас	roinverte	brates	MW.			Day		Temp.
Planning Watersho Station	ed #		D84 1	D50 +	Sediment - <0.85 <4.7	CV% +	CuFt/ 100'	Richness †	Simpson †	Hllsenhoff	С	F	Avg. C	Hig F	jh C	F
Station Average	4		267	52	32.2% 52.79	% 0.9%	1,008	23	0.78	1.96					21.1	70.0
Nanning 2	123	1996	63	31	37.6% 60.29	%		23	0.85	1.55						
Nanning 2	123	1997	136	40				25	0.90	1.74						
Station Average	123		100	36	37.6% 60.2%	%		24	0.88	1.65						
Dean Creek		6 Units	211	47	34.0% 55.29	% 0.9%	1,008	24	0.81	1.85					21.1	70.0
Planning Watershe	d: Howe	Creek														
Howe1	124	1996	187	73	34.3% 46.4%	6		23	0.83	2.00						
Howe1	124	1997	94	32		0.9%	796	20	0.85	2.03						
Station Average	124		141	53	34.3% 46.4%	% 0.9%	796	22	0.84	2.01						
Howe Creek		2 Units	141	53	34.3% 46.4%	6 0.9%	796	22	0.84	2.01						
Planning Watershe	ed: New b	erg														
Stronas 1	93	1995									15.5	60.0	16.5	61.7	17.0	62.7
Station Average	93										15.5	60.0	16.5	61.7	17.0	62.7
NF Stronas2	94	1995									14.1	57.4	14.2	57.6	14.3	57.8
Station Average	94										14.1	57.4	14.2	57.6	14.3	57.8
Stronns2	115	1995	137	96				23	0.84	1.80	14.1	57.4			14.4	57.9
Stronns2	115	1996	156	68	45.3% 53.1%			23	0.90	1.43						
Stronas 2	115	1997	73	41		1.2%	250	23	0.85	1.52						
Station Average	115		122	68	45.3% 53.1%		250	23	0.86	1.58	14.1	57.4			14.4	57.9
Newberg		5 Units	122	68	45.3% 53.1%	6 1.2%	250	23	0.86	1.58	14.6	58.2	15.4	59.7	15.2	59.4
Eel Delta		13 Units	174	54	36.3% 53.0%	6 1.0%	685	23	0.83	1.81	14.6	58.2	15.4	59.7	16.7	62.1
Hydrologic Unit: Gia	nts Ave.															
Planning Watershe	d: Fox C	Camp														
Bull F&G 1	69	1991			29.3% 42.4 %	6										
Station Average	69				29.3% 42.4%	6										
_ Squaw 1 (61% OG)	102	1991			17.9% 31.6%	6										
Squaw1 (61% OG)	102	1995	106	71				26	0.92	1.81	17.2	62.9	16.8	62.3	17.4	63.2
Squaw 1 (61% OG)	102	1996	104	79	28.3% 48.5%		4	22	0.85	1.36					17.5	63.5
Squaw1 (61% OG)	102	1997	58	33		0.7%	1.779	27	0.81	2.44						
Station Average	102		89	61	23.1% 40.0%		1,779	25	0.86	1.87	17.2	62.9	16.8	62.3	17.4	63.4
<u>Cuneo</u>	137	1996	267	31	22.2% 34.3%	6 0.6%		27	0.82	1.94						
<u>Cuneo</u>	137	1997	118	20				23	0.78	2.21						

Hydrologic Unit Planning Watershee Station	Station d #	Year	Cob D84		Fine Sediment - <0.85 <4.7	Complexity CV% +	y LWD CuFt/ 100'		croinvertel Simpson t		MW C	AT F		Day Hig F	High Jh C	Temp. F
Station Average	137		193	26	22.2% 34.3%	% 0.6%		25	0.80	2.08						
Fox Camp		7 Units	131	47	24.4% 39.2%	6 0.7%	1,779	25	0.83	1.95	17.2	62.9	16.8	62.3	17.4	63.4
Planning Watershed	d: Myers	s Flat														
Canoe 1 (62% 0G)	103	1995	199	 8	18.3% 37.6%	6 1.6%		23	0.82	1.91					19.4	67.0
	.00	.000			.0.0,0				0.90	1.86	18.0	64.3	20.1	68.3	20.5	68.9
_ Canoe 1 (62% OG)	103	1996	199	98	18.3% 37.6%	6 1.8%		24	0.90	1.86	17.8	64.1	19.7	67.4	20.1	68.1
Canoe1 (62% OG)	103	1997	75	35		1.8%	1.546	25	0.88	1.93						
Station Average	103		161	76	18.3% 37.6%	6 1.6%	1,546	24	0.87	1.89	17.9	64.2	19.9	67.8	20.0	68.0
Myers Flat		4 Units	161	76	16.3% 37.6%	6 1.6%	1,546	24	0.87	1.89	17.9	64.2	19.9	67.6	20.0	68.0
Planning Watershed	l: Panth	er Gap														
Bull2	101	1995	1158	457				22	0.76	2.11						
Bull2	101	1996	1000	413		6		26	0.85	1.61	19.5	67.2	21.8	71.3	22.4	72.3
Bull2	101	1997	251	63				24	0.88	1.94						
Station Average	101		803	311	29.2% 47.9%	, 0		24	0.83	1.89	19.5	67.2	21.8	71.3	22.4	72.3
Panther Gap		3 Units	803	311	29.2% 47.9%			24	0.83	1.89	19.5		21.6	71.3		72.3
Planning Watershed	l: Weot	-				-										
Bull 1	100	1995	63	35	<u>_</u>			23	0.88	2.12	19 9	67.8	22.6	72 7	24 0	75 1
Bull1	100	1996	91	46	19.1% 39.1%	6		22	0.77	1.66			25.1			
Bull1	100	1997	64	24				22	0.86	2.21						
Station Averaae	100		73	35	19.1% 39.1%	6		22	0.84	2.00	20.2	68.4	23.9	75.0	24.7	76.5
Cow 1 (93% OG)	105	1995	132	58				31	0.93	1.81						
Cow 1 (93% OG)	105	1996	142	79	21.9% 36.6%	6 1.2%		31	0.93	1.48	16.4	61.6	17.9	64.2	18.3	65.0
Cow 1 (93% OG)	105	1996	142	79	21.9% 36.6%			31	0.93	1.48	16.4	61.5		63.9	18.1	64.6
Cow 1 (93% OG)	105	1997	87	30		0.7%	1,187	24	0.84	2.65					. •	
Station Average	105		126	62	21.9% 36.6%		1,187	29	0.90	1.86	16.4	61.5	17.8	64.0	18.2	64.8
Weott		7 Units	103	50			1,187	26	0.86	1.92	18.3	65.0	20.8	69.5	21.5	70.6
Planning Watershed	l: Whitt	emore G					•									
Redwood Cr F&G 1	65	1990			21.8% 40.3%	, 0										
Redwood Cr F&G 1	65	1994			,	-		29	0.91	1.43						
Station Average	65				21.8% 40.3%	, 0		29	0.91	1.43						
Whittemore Grove		2 Units			21.8% 40.3%			29	0.91	1.43						
Giants Ave.		23 Units	233	96	22.6% 39.3%		1,504	25	0.86	1.89	18 2	64 R	20.2	66 4	20.3	68.6

Hydrologic Unit Planning Watersh Station	Station ed #	Year		bel D 50 +	Fine Sediment - <0.85 <4.7	Complexity CV% +	LWD CuFt/ 100'		Croinverte Simpson †		MW. C	AT F	7 [Avg. C	Day Hiç F		Temp. F
Hydrologic Unit: La	rabee Cr	•										_				
Planning Watersh	ed: Lara	bee														
Larabee 1	2	1994	165	61	9.0% 22.2%	, 0		24	0.87	2.27						
<u>Larab</u> eel	2	1995	146	60				23	0.88	2.13	21.3	70.3	26.2	79.2	27.1	80.7
Larabeel	2	1996	163	51	18.0% 36.3%	, 0		25	0.91	1.99	23.3	74.0	29.2	84.5	29.7	85.4
<u>Larab</u> eel	2	1997	244	65		2.4%	115	18	0.80	1.97						
Station Average	2		180	59	13.5% 29.3%	2.4%	115	23	0.87	2.09	22.3	72.1	27.7	81.9	28.4	83.1
Scott 1	99	1995									14.0	57.3	14.9	58.8	15.4	59.7
_ Scott 1	99	1996									14.4	57.9	14.7	58.4	14.8	58.7
Station Average	99										14.2	57.6	14.8	58.6	15.1	59.2
Larabee		6 Units	180	59	13.5% 29.3%	2.4%	115	23	0.87	2.09	18.3	64.8	21.2	70.2	21.7	71.1
Larabee Cr		6 Units	180	59	13.5% 29.3%	2.4%	115	23	0.87	2.09	18.3	64.8	21.2	70.2	21.7	71.1
Hydrologic Unit: Lo	wer Eel															
Planning Watersh	ed: Pepp	erwood														
Bear Cr 1	89	1995													21.9	71.4
Bear Cr 1	89	1996									17.4	63.4	20.3	68.5	20.7	69.3
Station Average	89										17.4	63.4	20.3	68.5	21.3	70.4
BearCr2	107	1995	115	57				26	0.91	1.88						
<u>BearC</u> r2	107	1996	85	44	17.3% 36.9%	, D		35	0.90	1.60						
<u>BearC</u> r2	107	1997	60	20		0.4%	1.979	27	0.86	2.16						
Station Average	107		87	40	17.3% 36.9%	0.4%	1,979	29	0.89	1.88						
BearCr3	114	1995	188	97				26	0.88	1.69						
BearCr3	114	1996	141	69	14.3% 31.2%	, D		30	0.89	1.94						
<u>BearC</u> r3	114	1997	67	23				28	0.85	2.29						
Station Average	114		132	63	14.3% 31.2%			28	0.87	1.97						
Shively 1	130	1996	89	42	15.3% 27.2%)		25	0.86	1.51						
Shivelv 1	130	1997	88	38		0.8%	108	31	0.88	1.47						
Station Average	130		89	40	15.3% 27.2%	0.8%	108	28	0.87	1.49						
Pepperwood		10 Units	104	49	15.6% 31.8%	0.6%	1,043	29	0.88	1.82	17.4	63.4	20.3	68.5	21.3	70.4
Planning Watersho	ed: Scoti	ia														
Monument2	106	1995	272	85				32	0.90	1.84						
Monument2	106	1996	217	60	23.0% 37.8%	1.1%		30	0.87	1.82	15.8	60.4	19.0	66.3	19.5	67.0
Monument2	106	1997	270	67		1.0%	582	20	0.88	1.81	. 3.0		. 2.0	- 3.3	. 5.3	•

Hydrologic Unit Planning Watersl Station	Station ned #	Year	Cob D84 +		Fine Sediment - <0.85 <4.7	Complexity CV% +	y LWD CuFt/ 100'		Croinverte		MW C	AT F		Day Hiç F		Temp. F
Station Average	106		253	71	23.0% 37.8%	1.1%	582	27	0.88	1.82	15.8	60.4	19.0	66.3	19.5	67.0
Scotia		3 Units	253	71	23.0% 37.8%	1.1%	582	27	0.88	1.82	15.8	60.4	19.0	66.3	19.5	67.0
Planning Watersh	ed: Staff	ord														
Twin_1	95	1995													21.4	70.6
Twin_1	95	1996									16.3	61.4	20.0	67.9	20.5	68.8
Station Average	95										16.3	61.4	20.0	67.9	20.9	69.7
Stafford		2 Units									16.3	61.4	20.0	67.9	20.9	69.7
Lower Eel		15 Units	145	55	17.5% 33.3%	0.8%	890	28	0.88	1.62	16.5	61.7	19.8	67.6	20.8	69.4
Hydrologic Unit: Se	equoia															•
Planning Watersh	ed: McCa	nn _	_													
Thompson 1	126	1996	156	62	19.6% 33.3%)		31	0.91	1.74						
Thompson1	126	1997	163	54				29	0.88	1.74						
Station Average	126		160	58	19.6% 33.3%	,		30	0.90	1.74						
McCann		2 Units	160	58	19.6% 33.3%			30	0.90	1.74						
Planning Watersh	ed: White	House														
Newman1	122	1996	96	58	16.6% 26.0%			28	0.93	1.54						
Newman1	122	1997	78	36		0.9%	130	32	0.92	1.67						
Station Average	122		88	47	18.6% 26.0%	0.9%	130	30	0.92	1.60						
White House		2 Units	88	47	16.6% 26.0%	0.9%	130	30	0.92	1.60						
Sequoia		4 Units	124	53	18.1% 29.6%	0.9%	130	30	0.91	1.67						
Eel WAA		61 Units	187	71	23.4% 39.5%	1.1%	862	26	0.86	1.66	17.3	63.2	19.6	67.7	20.0	68.1
Hydrologic Unit: Be	ar River															
Planning Watersh	ed: Beer	Bottle														
Bear River 1	1	1994	129	52	12.4% 26.1%			25	0.86	2.11	17.2	63.0	21.1	70.1	21.9	71.5
Bear River 1	1	1995	205	47				22	0.87	2.08					23.0	73.4
Bear River 1	1	1996	163	54	15.1% 27.1%			31	0.87	1.88	19.5	67.2	23.9	75.0	24.7	76.4
Bear River 1	1	1997	150	38		1. 0%	560	25	0.88	1.82						
Station Average	1		162	48	13.7% 26.6%	1.0%	560	26	0.87	1.97	18.4	65.1	22.5	72.5	23.2	73.8
Beer Bottle		4 Units	162	48	13.7% 26.6%	1.0%	560	26	0.67	1.97	18.4	65.1	22.5	72.5	23.2	73.8

Hydrologic Unit Planning Watershe Station	Station d #	Year	Cok D84 +		Fine Sediment - <0.85 <4.7	Complexity CV% +	LWD CuFt/ 100'		Croinverteb SImpson F		MW C	AT F	Avg.	Day Hiç F		Temp. F
Planning Watershe	d: Happ	y Valley	/													
Bear River 2	97	1995									16.6	61.8	20.5	69.0	21.4	70.5
Bear River 2	97	1996													21.3	70.3
Station Average	97										16.6	61.8	20.5	69.0	21.3	70.4
Harmonica 1	131	1996	112	53	15.9% 27.39			23	0.90	1.59						
Harmonica 1	131	1997	52	13		0.8%	401	23	0.87	1.93						
Station Average	131		82	33	15.9% 27.39	% 0.8%	401	23	0.88	1.76						
Pullen 1	134	1996	114	63	12.9% 25.09	%		24	0.89	1.66						
Pullen 1	134	1997	50	23		0.9%	698	22	0.89	2.00						
Station Averaae	134		82	43	12.9% 25.09	% 0.9%	698	23	0.89	1.83						
Happy Valley		6 Units	82	38	14.4% 26.19	% 0.8%	550	23	0.89	1.80	16.6	61.8	20.5	69.0	21.3	70.4
Bear River		10 Units	122	43	14.1% 26.49	% 0.9%	553	24	0.88	1.88	17.8	64.0	21.9	71.3	22.5	72.4
Hydrologic Unit: NF I	Mattole	River														
Planning Watershee	d: Rainl	woo														
Rodgers 1	29	1994	255	67	30.4% 47.49	%		30	0.85	1.99						
Rodaers 1	29	1995	450	112				21	0.70	1.94						
Rodners 1	29	1996	296	82	24.1% 40.49	%		24	0.81	1.41	17.9	64.3	22.2	72.0	23.1	73.6
Rodners 1	29	1997	220	56				36	0.87	2.16						
Station Average	29		305	79	27.2% 43.99	%		28	0.81	1.87	17.9	64.3	22.2	72.0	23.1	73.6
Alwardt 1	30	1994	270	27	17.5% 36.49	%		35	0.87	1.96						
Alwardt 1	30	1995	225	22				28	0.90	2.15						
Alwardt '	30	1996	450	130	17.1% 32.89	%		29	0.88	1.89						
Alwardt 1	30	1997	345	55				36	0.89	2.08						
Station Average	30		323	59	17.3% 34.69			32	0.89	2.02						
Rainbow		8 Units	314	69	22.3% 39.29			30	0.85	1.95	17.9	64.3	22.2	72.0	23.1	73.6
NF Mattole River		8 Units	314	69	22.3% 39.29	%		30	0.85	1.95	17.9	64.3	22.2	72.0	23.1	73.6
Hydrologic Unit: Upp	er NF N	lattole														
Planning Watershee	d: Rattle	esnake	Creek													
Rattle Snake F&G	62	1991			13.3% 32.69	%										
Rattle Snake F&G	62	1993													19.0	66.2
Rattle Snake F&G	62	1994						23	0.87	1.89					20.6	69.0
Rattle Snake F&G	62	1994						27	0.87	1.69					20.6	69.0

Hydrologic Unit Planning Watershe Station	Station ed #	Year	Cobbel D84 D50 + +	Sedim		CV%	ty LWD CuFt/ 100		roinverte SImpson +		MWAT C F		_		Temp. F
Rattle Snake F&G	62	1996		8.0%	26.2%										
Station Average	62			10.7%	29.4%			25	0.87	1.79				20.0	68.1
Rattlesnake Creek		5 Units		10.7%	29.4%			25	0.87	1.79				20.0	68.1
Planning Watershe	d: Tent	City													
Oil F&G	63	1991		19.2%	40.7%									26.7	80.0
Oil F&G	63	1993												25.0	77.0
Oil F&G	63	1994						23	0.89	1.86				25.6	78.0
Oil F&G	63	1994						21	0.88	1.87				25.6	78.0
Oil F&G	63	1996		8.7%	26.9%										
Station Average	63			14.0%	33.8%			22	0.89	1.86				25.7	78.3
Green Ridge F&G	64	1991		23.0%	52.1%										
Green Ridne F&G	64	1993												18.9	66.0
<u>Green</u> Ridae F&G	64	1994						36	0.94	1.54				21.4	70.5
Station Average	64			23.0%	52.1%			36	0.94	1.54				20.1	68.3
Tent City		8 Units		17.0%	39.9%			27	0.90	1.75				23.8	74.9
Upper NF Mattole		13 Units		14.5%	35.7%			26	0.89	1.77				22.6	72.6
Bear Mattole WAA		31 Units	218 56	16.7%	33.9%	0.9%	553	27	0.87	1.88	17.8 64.	1 21.9	71.5	22.6	72.6
Hydrologic Unit: Out	let Cr														

Planning Watershed: Willits Creek

r lanning traction		0.00.0			
Willits F&G 3	75	1991	21.9% 30.0%		
Station Average	75		21.9% 30.0%		
Willits F&G 4	76	1991	21.8% 35.3%		
Station Average	76		21.8% 35.3%		
Willits F & G 5	77	1991	25.5% 35.6%		
Station Average	77		25.5% 35.6%		
Willits F&G 6	78	1991	26.7% 39.1%		
Station Average	78		26.7% 39.1%		
Willits Creek		4 Units	24.0% 35.0%		
Outlet Cr		4 Units	24.0% 35.0%		

Hydrologic Unit: Richardson

Planning Watershed: Miller Creek

Hydrologic Unit Planning Watersho Station	Station ed #	Year	Cobbel D84 D50 + +	Fine Sediment - <0.85 < 4.7	Complexity CV% +	y LWD CuFt/ 100'		SImpson		MW. C	AT F	Avg.	ay Hig F	High Jh C	Temp. F
Redwood Cr F&G 2	41	1990		15.0% 30.89	%										
Redwood Cr F&G 2	41	1994					29	0.87	1.43						
Station Average	41			15.0% 30.89			29	0.87	1.43						
Redwood Cr F&G 3	70	1990		25.7% 42.09	6										
Redwood Cr F&G 3	70	1996								17.4		18.6	65.5	19.1	66.4
Station Average	70			25.7% 42.09	<u>/</u> 6					17.4	63.3		65.5	19.1	66.4
Miller Creek		4 Units		20.4% 36.4%	6		29	0.87	1.43	17.4	63.3	18.6	65.5	19.1	66.4
Planning Watershe	d: Uppe	Sprou	t Creek												
Little Sproul F&G 1	54	1994					32	0.92	1.82						
Little Soroul F&G 1	54	1994					31	0.86	1.88						
Little Sproul F&G 1	54	1996								19.2	66.6	21.0	69.9	21.7	71.1
Station Average	54						32	0.89	1.85	19.2	66.6	21 .0	69.9	21.7	71.1
Little Soroul F&G 2	55	1994					26	0.74	1.97						
Station Average	55						26	0.74	1.97						
Sproul F&G 4	79	1990		21.8% 42.2%	6										
Station Average	79			21.8% 42.2%	6										
Soroul F&G 6	80	1990		26.2% 44.0%	6										
Station Average	80			26.2% 44.0%	6										
Sproul F&G 7	81	1990		23.4% 38.7%	6										
Station Average	81			23.4% 38.7%	6										
Upper Sprout Creek		7 Units		23.8% 41.6%	6		30	0.84	1.89	19.2	66.6	21.0	69.9	21.7	71.1
Richardson		11 Units		22.4% 39.5%	6		30	0.85	1.76	18.3	65.0	19.8	67.7	20.4	68.8
Hydrologic Unit: Upp	oer Matto	le													
Planning Watershe	d: Thom	pson C	reek												
Baker F&G 1	56	1994					33	0.91	1.56						
Station Average	56						33	0.91	1.56						
Baker F&G 2	57	1994					37	0.88	1.83						
Station Average	57						37	0.88	1.83						
Baker F&G 3	58	1994					25	0.85	1.89						
Station Average	58						25	0.85	1.89						
Baker F&G 4	59	1994					33	0.91	1.58						
Station Average	59						33	0.91	1.58						

Hydrologic Unit	Station	Year	С	obbe	el	Fine	C	omplexity	LWD	Mac	roinverte	brates	MWAT	7 Day	Н	igh T	emp.
Planning Watershed Station	#		D84 +	e s +	O Se <0.8	diment 5 <4		+ £Α%	CuF t/ 100'	Richness +	Simpson +	Hilsenhoff	8 F	Avg. Hig E F	gh :	3	F
Thompson Creek		4 Units	s							32	0,89	1.71					
Upper Mattole		4 Units	s							32	0,89	1.71					
Outside Bioregion		19 Unit	S		23	.1 % 37	.5%			ეე	0.87	1.75	1 8.3 65	. 0 1 9,8 67	. 7 Z C) , d <i>(</i>	8 4 8
All (Mad to Mattole)		287 Units	s 18	7 6	63 21 .	3% 38	.6%	1.1%	858	28	0.87	1.75	1 6.7 62.0) 18 .7 6 9	. 1	19.9	67.8